

SUBSTITUTE DRAWING





Fig. 1

A cross-sectional view of a mechanical assembly. A horizontal member 32 is positioned at the top. Below it, a vertical member 43 is shown. To the left of the vertical member 43 is a component 44. To the right of the vertical member 43 is a component 42. Below the vertical member 43 is a component 40. At the bottom of the vertical member 43 is a component 36. To the right of the vertical member 43 is a component 46. To the right of the component 46 is a component 34. Below the component 34 is a component 38. At the bottom of the component 34 is a component 48. A dashed line 14 is shown on the right side of the assembly.

A schematic diagram of a device 14, showing a cross-section of a substrate 50 with a central layer 36 containing circular elements. Wires 46 connect these elements to a top surface. Dimensions 51, 52, and 53 are indicated.

Fig. 3



500 micron

FIG. 4

SUBSTITUTE DRAWING

SUBSTITUTE DRAWING




FIG. 5a




FIG. 5b




FIG. 5c

BEST AVAILABLE COPY